COMPLETION REPORT

1	Name of the work	Improvements and maintenance of Culvert at Santhosh nagara in ward no 13 Mallasandra Shettyhalli Sub division
2	Sanctioned Estimate No. & Date	EE/DO/TS/68/18.19. Dt. 30.01.2019
3	Head of Account which is chargeable	SC/ST Category Reserved work
4	Instrument Order NO. & Date	EE/DO/WE/424/18.19. dt 18/10/19
5	Name Of Contractor	Sri. D. V. Kumar, #657, 5th Main road, LG Ramanna Layout, Laggere, Bangalore 560058
6 a	Time Stipulated for Completion of work	90 days
b	Delay in Exculpation of Work	—
7	Measurement recorded in	14.01.2020
8	Check Measurement of the Asst	14/1/2020 Kumappa. AEE
9	Name of the office/official in charge of the work	AEE. BBMP. As below Shettyhalli Sub Division Engg
10	a) Asst. Eng/junior Eng	Venkateshappa
	b) Asst. Exe Engineer	Kumappa

Sanctioned Estimate Amout	Amout Claims As per Actually Vide As per bills	Excess	Savings
10.00 Lacs	1017823	—	—

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER. ASSIATANT EXECUTIVE ENGINEER EXECUTIVE ENGINEER

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಬ್ಬಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner